




B9Creations Recommended Burnout Schedule




SPECIFIC GRAVITY for Casting Resins: 1.06

All ramp rates set at 28°F per minute

Visit b9c.com/jewelry for °C burnout schedule.



B9Creations Recommended Burnout Schedule



SPECIFIC GRAVITY for Casting Resins: 1.06
All ramp rates set at 2°C per minute